

MODEL VM196 HAS BEEN DISCONTINUED AND REPLACED WITH MODEL VM197

The Model VM196 Valve Plaster Guard is now discontinued and has been replaced with the Model VM197.

The function is the same, but there is a slight modification. The VM197 features a recessed handle, improving its ability to prevent plaster and wallboard mud from entering the wall inlet during construction. The color has also changed from almond to black.



Model VM197
Valve Bracket Plaster Guard

MODEL	STATUS	UPC CODE
VM196	DISCONTINUED	727066065766
VM197	ACTIVE	727066065766



Model VM196
Valve Bracket Plaster Guard (DISCONTINUED)

All these brands are now under one name, Linear.